



# iPega 9023 Disassembly

This guide will give step by step instructions to repair sticky ABXY buttons.

Written By: AndrewGueguen





## TOOLS:

- [Phillips #0 Screwdriver](#) (1)
  - [64 Bit Driver Kit](#) (1)
-




## Step 1 — Remove Cover



- Remove the four screws with the 3 mm Triage driver from the backside of the controller.
- Use the 3 mm Triage Driver for the screws in red.
- Use the 4 mm nut driver as a makeshift extension to remove the screws in green.

## Step 2 — Removing the logic board



- Remove the 4 screws holding the logic board in place.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-20 06:31:44 AM.